HABS No. NJ-964

HABS NJ, II-TRET, JJ.

16 East State Street (Commercial Building)

Trenton

Mercer County New Jersey

## PHOTOGRAPHS

WRITTEN HISTORICAL AND DESCRIPTIVE DATA

HISTORIC AMERICAN BUILDINGS SURVEY
MID-ATLANTIC REGION, NATIONAL PARK SERVICE
DEPARTMENT OF THE INTERIOR
PHILADELPHIA, PENNSYLVANIA 19106

Form 10-920 (June 1983)

## UNITED STATES DEPARTMENT OF THE INTERIOR NATIONAL PARK SERVICE

HABS NJ, TRET, 22.

December 1987


## ARCHITECTURAL DATA FORM

STATE	COUNTY	TOWN OR VICINITY
New Jersey	Mercer	Trenton
HISTORIC NAME OF STRUCTURE (INCL	UDE SOURCE FOR NAME)	HABS NO
		- NJ-964
16 East State Street (Commercial Building) SECONDARY OR COMMON NAMES OF STRUCTURE		
COMPLETE ADDRESS (DESCRIBE LOCATION FOR RURAL SITES)  16 East State Street (Commercial Building)		
To East State Street (Commercial Editating)		
DATE OF CONSTRUCTION (INCLUDE SOURCE)  ARCHITECT(S) (INCLUDE SOURCE)		
ca. 1926 (Deeds; Photo collec- Not known tion of Trenton Public Library)		
SIGNIFICANCE (ARCHITECTURAL AND	HISTORICAL INCLUDE ORIGINAL USE	OF STRUCTURE)
This commercial building was erected about 1926, and for nearly half a		
century, its primary retail tenant was a franchisee of the Florsheim Shoe Corp It occupies the site of a mid-19th century commercial building which was the		
home of MacCrellish & Quigley, an important Trenton printing firm which was		
STYLE (IF APPROPRIATE)		any years the state printer.
MATERIAL OF CONSTRUCTION (INCLU	DE STRUCTURAL SYSTEMS	
Cut limestone facade. English-bond brick rear elevation with brownstone		
_sills and lintels.		
HAPE AND DIMENSIONS OF STRUCTURE (SKETCHED FLOOR PLANS ON SEPARATE PAGES ARE ACCEPTABLE)		
Rectangular structure. Facade=20'. Depth=102.46'.		
EXTERIOR FEATURES OF NOTE		
Facade is one large bay with centered window wall of grouped sash and		
fixed panes. Neoclassical moldings, enframing pilasters, modillion cornice and parapet articulate the planar wall surface.		
INTERIOR FEATURES OF NOTE (DESCRIBE FLOOR PLANS, IF NOT SKETCHED)		
Walls covered with sheetrock, floors with wall-to-wall carpeting. The		
first floor is a retail space greatly altered over time. The upper floors are		
divided into front and rear offices.		
MAJOR ALTERATIONS AND ADDITIONS WITH DATES		
Storefront altered with recessed bulkhead, metal panels and roll-down		
metal security door, all ca. 3rd quarter 20th century. All historic interior features and finishes removed, date unknown.		
PRESENT CONDITION AND USE		
Fair to good condition. Retail and office use until demolition,		
September, 1987.		
OTHER INFORMATION AS APPROPRIATE		
The earlier, more historically interesting building is known to have been demolished about 1925 via a photograph of the empty lot in the Trentoniana		
Collection of TFPL.		
SOURCES OF INFORMATION (INCLUDING LISTING ON NATIONAL REGISTER, STATE REGISTERS, ETC.)		
Sended St. 111 Grant International St. 110 St. 110 International S		
Trenton Directory 1920-1950		
	. 119 (October 20, 1926).	
COMPUED ACCULATION		I DATE

Robert P. Guter, ACROTERION Historic Preservation Consultants, Morristown, NJ

Site Plan

## E. Hanover Street



E. State Street

16 East State Street (Commercial Building) HABS No. NJ- 964 (page 3)

Floor Plan

